

Date: April 3, 2023

From: Sue Kutay, Global Product Marketing Manager

To: Customers of KODAK FLEXCEL NXH Plates

Subject: Cosmetic Color Difference to FLEXCEL NXH 1.70 MM (0.067") Plates

To our valued customers:

In your upcoming orders, you may notice a slight color shift in your FLEXCEL NXH 1.70 plates. The color shift is cosmetic only and will not impact any performance characteristics of the plate and you should confidently utilize them as normal. We have identified the root cause and taken corrective actions to prevent further instances. Figure 1 illustrates the color shifts that may be observed, you will notice it is most apparent in the raw plate.




Figure 1 Side by side color comparison of the affected product with the reference plate.

What action do I need to take?

Please share this information throughout your operation as appropriate. Continue to use the plates per your normal practice. There is no need to return the plates as the color difference is purely cosmetic in nature and the plates will deliver the same high-quality performance. As always, we recommend checking your exposure settings when you receive a new batch, according to our best practice guidelines.

What products are impacted by the change?

The following table outlines which products contain the color shift.

| Plate and Thickness | Plate Size | Catalog Number | Batch Code |
|------------------------------------|--------------------------------|----------------|--|
| FLEXCEL NX Plate 1.70 MM/0.067" | 42" x 60" 1067 mm x 1524 mm | 7873763W | 31042L12 31042L14 31042L16 31042L18 31042L20 31042L22 31052L00 31052L02 31052L04 31052L06 31052L08 |

If you have any questions regarding this communication, please contact your local sales manager or technical application specialist.

Thank you once again for both your understanding and your continued business with us.