www.miraclon.com 1057 E Henrietta Road, Suite 600 Rochester, NY 14650



## June 2023

## **Re: Food Safety**

KODAK LEXCEL NX plates do not come into direct contact with the exterior surfaces of packaging media during printing and the plate coating itself is not transferred to the packaging during production.

Likewise, KODAK FLEXCEL plate processing solutions and KODAK FLEXCEL thermal imaging layer film (TIL/TIL-R) do not come into direct contact with the exterior surfaces of packaging media and are not transferred to the packaging during production.

As a result, KODAK FLEXCEL NX plates and TIL/TIL-R film do not fall within the scope of the EU Framework Regulation (EC) No 1935/2004, nor of the Swiss Ordinance on Materials and Articles in Contact with Food (SR 817.023.21), nor of the Dutch Commodities Act on food contact materials (*kenmerk* 328583-117560-VGP).

As part of our product stewardship and regulatory compliance efforts, we continue to monitor potential regulatory, safety, health and environmental impact of using our products.

If you have additional questions or require further assistance, please feel free to email EAMERcustomercare@miraclon.com.